United States of America

Department of Transportation—Jederal Aviation Administration

Supplemental Type Certificate

Number SA7299SW-D

This certificate, issued to

Dassault Falcon Jet P.O. Box 967

Little Rock, Arkansas 72203

cortifies that the change in the type design for the following product with the limitations and conditions therefor as specified hereon meets the airworthiness requirements of Part 25 of the Federal Aviation Regulations.

Original Product - Trype Cortificate Number:

A46EU

Make:

Dassault Aviation

Model:

Mystere - Falcon 50

Description of Trype Design Change:

Installation of the No. 2 Emergency Power Supply System in accordance with Drawing List Report No. F50-01016, Revision M dated 3-30-96, or later FAA approved revision.

Limitations and Conditions: See Page 2.

This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked, or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.

Date of application:

September 17, 1990

Date reissued :

February 7, 1991

Date amended: 7-12-93, 7-15-96 Rev. 2

Date of issuance:

By direction of the Administrator

Enhew E. Bourne

Andrew A. Boersma

DASSSW COORDINATOR

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.

Makel States of Charries

Department of Transportation—Jederal Aviation Administration

Supplemental Type Certificate

(Continuation Sheet)

Number

SA7299SW-D Revision 2

Limitations and Conditions:

- 1) FAA Approved Airplane Flight Manual Supplement Report Number 35263-2, Revision A dated 7-12-93 or later FAA approved revision, is required when the F50-01016-505 installation is utilized.
- 2) FAA Approved Airplane Flight Manual Supplement Report No. 35263-3, dated July 15, 1996 or later FAA approved revision, is required when the F50-01016-507 installation is utilized.
- 3) Compatibility of this modification with other previously approved modifications must be determined by the installer.
- 4) This STC utilizes STC SA4573SW, issued 12-21-81, as a certification basis of compliance.
- 5) Periodic Maintenance Testing of the PS-855 Power Supply is required in accordance with J.E.T. Installation Manual 24-30-06.

INSTRUCTIONS: The transfer endorsement below may be uthe transfer of this Supplemental Type Certificate.	used to notify the appropriate FAA Regional Office of		
TRANSFER ENDORSEMENT Transfer the ownership of Supplemental Type Certificate Number			
		to (Name of transferee)	
		(Address of transferee)	(Number and street)
	City, State, and ZIP code)		
from (Name of grantor) (Print or type)			
(Address of grantor)	(Number and street)		
10	City, State, and ZIP code)		
Extent of Authority (if licensing agreement):			
Date of Transfer:			
Signature of grantor (In ink):			